

Quote

01/10/2024

To:

1

Heather Gardens Cormac Ronan Project:

Heather Gardens - Walk in Freeer

From:

Pueblo Hotel Supply

Eric Landauer dba Grady's

170 Greenhorn Drive Pueblo, CO 81004 (719)542-8853

All quotes are valid within the same month quoted. If purchasing after the month of the quote, manufacturer increases may apply.

Due to current supply chain issues, and unpredictable freight increases, all freight quotes are **estimates only.** Exact freight charge will be calculated and added to invoice at time of actual shipment.

Orders paid by credit card will have a 2.9% processing fee added at time of transaction.

Item Qty Description Sell Sell Total

1 ea WALK IN FREEZER, MODULAR, REMOTE

\$19,420.73

\$19,420.73

Arctic Industries Model No. BL812-F-R Walk-In Freezer, Indoor, 7' 11"W x 11' 9"L x 7' 8-1/2"H, (-10° F holding), with floor, urethane foam insulated cam-lock panels with 26 GA embossed metal interior & exterior finish, urethane foam insulated floor with smooth aluminum finish, key lock handle, digital thermometer, light switch, inside safety release, door heater, pressure relief valve, 34" x 78" door with interior & exterior 24" high diamond kick plates, remote pre-assembled refrigeration, R448/449 refrigerant, NSF, UL, EISA

- 1 ea Manufacturing Note
- 1 ea Pricing is valid for 60 days upon receipt of pruchase order AND approved drawing (if applicable). Order must ship per our current lead time or pricing will be subject to change. All shipments will be FOB Miami, FL or Azusa, CA.
- 1 ea Please check local building codes for installations. Arctic is not responsible for any local codes or municipality laws that may affect the approval at the job-site by the permitting authority.
- 1 ea Shipping to California, Oregon, and Washington may require seismic engineering. Please verify local codes for requirements and contact factory for add-ons
- 1 ea 5 year compressor warranty, 1 year parts and labor, 15 year panel warranty

Total

1 ea (-R) This walk-in is designed for Indoor installation. To install the walk-in outdoors, please select the Outdoor Installation package under accessories, the condensing unit can be installed outdoors 1 ea Electrical Details 1 ea Lighting - 115v/60/1-ph, [refer to spec sheet for details] 1 ea Evaporator Coil - 115v/60/1-ph, [refer to spec sheet for details] 1 ea Condensing Unit - 208-230v/60/1-ph, [refer to spec sheet for details] 1 ea 34" x 78" door [standard] 1 ea Strip curtain for 34" door 1 ea Interior Smooth Stainless Steel ramp for 34" Door \$243.90 \$243.90 1 ea Door hinged on left 1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78 S22,048.78 Installation \$7,500.00	Item	Qty	Description	Sell	Sell Total
1 ea Lighting - 115v/60/1-ph, [refer to spec sheet for details] 1 ea Evaporator Coil - 115v/60/1-ph, [refer to spec sheet for details] 1 ea Condensing Unit - 208-230v/60/1-ph, [refer to spec sheet for details] 1 ea 34" x 78" door [standard] 1 ea Strip curtain for 34" door \$243.90 \$243.90 1 ea Interior Smooth Stainless Steel ramp for 34" Door \$878.05 \$878.05 1 ea Door hinged on left 1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand		1 ea	in outdoors, please select the Outdoor Installation package under		
1 ea Evaporator Coil - 115v/60/1-ph, [refer to spec sheet for details] 1 ea Condensing Unit - 208-230v/60/1-ph, [refer to spec sheet for details] 1 ea 34" x 78" door [standard] 1 ea Strip curtain for 34" door \$243.90 \$243.90 1 ea Interior Smooth Stainless Steel ramp for 34" Door \$878.05 \$878.05 1 ea Door hinged on left 1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	Electrical Details		
1 ea Condensing Unit - 208-230v/60/1-ph, [refer to spec sheet for details] 1 ea 34" x 78" door [standard] 1 ea Strip curtain for 34" door \$243.90 \$243.90 1 ea Interior Smooth Stainless Steel ramp for 34" Door \$878.05 \$878.05 1 ea Door hinged on left 1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand		1 ea	Lighting - 115v/60/1-ph, [refer to spec sheet for details]		
1 ea 34" x 78" door [standard] 1 ea Strip curtain for 34" door \$243.90 \$243.90 1 ea Interior Smooth Stainless Steel ramp for 34" Door \$878.05 \$878.05 1 ea Door hinged on left 1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	Evaporator Coil - 115v/60/1-ph, [refer to spec sheet for details]		
1 ea Strip curtain for 34" door \$243.90 \$243.90 1 ea Interior Smooth Stainless Steel ramp for 34" Door \$878.05 \$878.05 1 ea Door hinged on left 1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	Condensing Unit - 208-230v/60/1-ph, [refer to spec sheet for details]		
1 ea Interior Smooth Stainless Steel ramp for 34" Door \$878.05 \$878.05 1 ea Door hinged on left 1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	34" x 78" door [standard]		
1 ea Door hinged on left 1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	Strip curtain for 34" door	\$243.90	\$243.90
1 ea 4' LED Light \$225.61 \$225.61 1 ea Outdoor Installation Package \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	Interior Smooth Stainless Steel ramp for 34" Door	\$878.05	\$878.05
1 ea Outdoor Installation Package \$1,280.49 1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	Door hinged on left		
1 ea NOTE: Outdoor packages include roof membrane, tie-downs, and door gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	4' LED Light	\$225.61	\$225.61
gutter 1 ea NOTE: To avoid ceiling failure or collapse due to snow and/or ice [not covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	Outdoor Installation Package	\$1,280.49	\$1,280.49
covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for additional information] 1 ea Liftgate delivery charge - not incldued in free freight program [NET] 1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	• •		
1 ea NOTE: Liftgate delivery is guaranteed for the refrigeration pallets ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	covered by panel warranty], accumulation of 3" or more must be carefully removed in a manner that does not cause damage [tears, punctures, etc.] to the membrane roof [Please contact factory for		
ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time of delivery to "break down" the pallet & unload the panels by hand Merchandise \$22,048.78		1 ea	Liftgate delivery charge - not incldued in free freight program [NET]		
• •		1 ea	ONLY. Pallets containing panels do not fit on liftgates & will need to be unloaded by hand. Ample manpower must be available at the time		
• •			Merchand	ise	\$22,048.78
					\$7,500.00

\$29,548.78

Pueblo Hotel Supply

Any and all damaged item(s) should be marked as such on delivery ticket and or refused and Grady's Restaurant and Bar Equipment should be notified immediately as to the extent of the damage so that we can address and work toward a solution immediately.

All packaging materials must be retained from damaged item(s) for freight inspector/adjuster claim.

Custom fabricated item(s) are <u>not</u> returnable. Buy-out item(s) may be returnable less the manufacturer's restocking fee, freight too and from, as well as any damages that may be incurred. The returned item(s) <u>must be new and unused.</u>

Credits for returned item(s) will only be given once the factory has issued credit to Grady's Restaurant and Bar Equipment

Freight is **not** included unless otherwise specified.

Price does <u>not</u> included fees, taxes, bond, permit, or licenses unless otherwise specified.



Acceptance:	Date:	
Printed Name:		
Project Grand Total: \$29,548.78		